



ESS (AC DC coupled) "Feed-in excess solar charger power" SOC calculation 25% too high!

Samstag, 10. August 2019 12:29



System/BatteryMonitor=Multi
(BYD Voltage Values are to slow to support feature "feedin Excess DC Charger")



Changed Battery Monitor back to CAN BMS

